

Inspection report

Client	Examiner	Date
F. Peterson	Car Check Frank/ F.	12.02.2025

EXAMINATION CONDITIONS

Conditions	VALUE
Weather conditions	Sunny
Daylight	Bright (daylight)
Is the vehicle clean?	Outside is dirty
Vehicle accessible and test drive?	Yes

VEHICLE DATA

Parameter	Value	Parameter	Value
Brand	BMW	VIN	WBA31CG40CG08803
Model	530 E X Drive	Car type	Estate car
Transmission	Automatik	First registration	03/22
Fuel	Petrol/Hybrid	Color exterior/interior	Blue, Black
Engine displacement	1.998 cm ³	Number of doors	5
Power	135 kW (183 HP)	Next TUV	10/26
Odometer	46.341 km	Emissions class	Euro 6
Previous owner	2	EU-Import	No, original German car

EQUIPMENT CHECK	Present	Functional
-Air conditioning	Yes	Yes
-Air suspension	Yes	-
- Ambient lighting	Yes	Yes
-Apple CarPlay	Yes	Yes
-Auto start-stop system	Yes	Yes
-Blind spot monitoring	Yes	Yes
-Bluetooth	Yes	Yes
-Cruise or adaptive control	Yes, adaptive	Yes
-Charging cables	Yes, 1 cable for home	Yes
-Digital radio	Yes	Yes
-Driver assistance systems	Yes, self steering	Yes
-Electric parking brake	Yes	Yes
-Electric seats	Yes, with memory	Yes
-Electric windows	Yes	Yes
-Emergency spare wheel	No, only repair kit	-
- Front parking sensors	Yes	Yes
-Rear parking sensors	Yes	Yes
-Head-up display	Yes	Yes
-Heated steering wheel	Yes	Yes
-Hill hold assist	Yes	Yes
-Isofix child seat anchors	Yes	Yes
-Keyless entry and start	Yes	Yes
-Lane keeping assist	Yes	Yes
-Leather seats	Yes	Yes
-LED or Xenon headlights	Yes, LED	Yes
-Massage seats	Yes, only front	Yes
-Navigation system	Yes	Yes
-Night vision assist	No	-
- Panoramic roof	Yes, sliding	Yes
-Park assist	Yes	Yes
-Power tailgate	Yes	Yes
-Rear-view camera	Yes, 360 camera	Yes
-Roof rails	Yes	-
- Seat heating	Yes	Yes
-Seat ventilation	Yes	Yes
-Sound system	Yes	Yes
-Sport seats	No	-
- Steering wheel heating	Yes	Yes
-Tow bar	No	No
-Traffic sign recognition	Yes	Yes
-USB ports	No, only USB-C	Yes
-Wireless charging	Yes	Yes

VEHICLE DOCUMENTS

Document	Details
COC	Yes
Vehicle registration document 1	Present
Vehicle registration document 2	Present
Manual	Present
TUV Certificate	Present
Service book	Digital
Service history up-to-date?	Yes

Tires

Set 1

Pos.	Brand	Type	Size	Depth / DOT
FL	Continental	Sommer	235 / 55 R18	6.5mm / 3322
FR	Continental	Sommer	235 / 55 R18	6,5mm / 3322
RL	Continental	Sommer	235 / 55 R18	2,9 mm / 3322
RR	Continental	Sommer	235 / 55 R18	2,9 mm / 3322

Set 2

Pos.	Brand	Type	Size	Depth / DOT
FL	Nexen	Winter	235 / 55 R18	5,9 mm / 3822
FR	Nexen	Winter	235 / 55 R18	5,9 mm / 3822
RL	Nexen	Winter	235 / 55 R18	6,2 mm / 3822
RR	Nexen	Winter	235 / 55 R18	6,2 mm / 3822

PAINT THICKNESS & CONDITION

Component	Paint layer thickness in µm	Repainted?	Damage / abnormalities
Hood	123µm	No	Chip stones
Fender front left	119 µm	No	-
Front right fender	124 µm	No	-
Door front left	345µm	Yes	Repainting, no color difference
Door Rear left	336µm	Yes	Repainting, no color difference
Door front right	116µm	No	-
Door rear right	125µm	No	-
Fender rear left	121µm	No	-
Fender rear right	123 µm	No	-
Roof	116 µm	No	-
Rear door	117 µm	No	-

BODY

Component	Condition	Damage / abnormalities
Front bumper	Damaged	Scratches
Rear bumper	Damaged	Scratches
Grill	-	-
Sill left	-	-
Sill right	-	-
Panel alignment	-	-

Lights

Component	Function	Damage / abnormalities
Headlights	-	-
Taillights	-	Glass broken
Brake lights	-	Glass broken
Reversing lights	-	-
Indicators	-	-
Hazard warning lights	-	-
Fog lights	-	-
Low beam	-	-
Interior lighting	-	-
Daytime running lights	-	-

Lights

Bodywork & exterior components

Component	Condition	Damage / abnormalities
Windshield	-	Chip stones
Window glazing	-	-
Windshield wipers	-	-
Seals	-	-
Central locking	-	-
Remote locking	-	-
Exterior mirrors	Damaged	Scratches

Rims

Position	Condition	Damage / abnormalities
Rim FL	-	-
Rim FR	-	-
Rim RL	-	-
Rim RR	-	-

Undercarriage & Drivetrain

Component	Condition	Damage / abnormalities
Wheel suspension	-	-
Shock absorbers	-	-
Springs	-	-
Brake discs	-	-
Brake pads	-	
Exhaust system	-	
Engine oil leakage	-	-
Gearbox oil leakage	-	-
Coolant fluid	-	-
Undercarriage general	-	-
Comments	-	-
	-	

Engine

Component	Condition
Engine fluid	-
Braking fluid	-
Coolant	-
Engine compartment condition	Dirty

SERVICE

Next inspection	06/2026
Next inspection	06/2026

TEST RUN / TEST DRIVE

Test drive conducted?	Yes	
Component	Condition	Note
Starter	-	-
Engine running	-	-
Steering	-	-
Clutch	-	-
Transmission	-	-
Speedometer	-	-
Spongy braking	-	-
Unusual noises	-	-
Timing chain/belt	-	-

INTERIOR

Component	Condition	Damage / abnormalities
Seat belts	-	-
Steering wheel	-	-
Dashboard	-	-
Heating/Ventilation	-	-
Controls	-	-
Power windows	-	-
Rearview mirror	-	-
Seats	-	-
Glove compartment	-	-
Floor	-	-
Interior rim	-	-
Headliner	-	-
Horn	-	-
Smell	-	-